

**⚠️⚠️ WARNING**

Quick  
Reference  
Guide

FLUKE®



+

-

Measure

1x

Measure

1x

12 1  $\frac{3}{8}$  in

+ -

1x

+ -

2x

12 1  $\frac{3}{8}$  in

Measure

1x

12 1  $\frac{3}{8}$  in

12 1  $\frac{3}{8}$  in

242  $\frac{3}{8}$  in


Measure

1x

-


21  $\frac{3}{8}$  in

100  $\frac{3}{8}$  in



The Meter produces a visible laser beam which emerges from the front of the Meter.

## Laser Distance Meter 414D




### Buttons

1. Measure/Min Max/Power On
2. Area/Volume/Indirect Measurement (Pythagoras)
3. Reference/Units
4. Plus (+)/Minus (-)
5. Clear/Off


Area  
Volume  
Height

$$1x = \square$$




Area  
Volume  
Height

$$2x = \square$$




Area  
Volume  
Height

$$3x = \triangle$$



Area  
Volume  
Height

$$4x = \triangle$$



Measure

